



Fuse taping method


Start by taping along the fuse on all four sides with fibre tape. Then do a 45 deg wrap around the fuse from the nose to tail.



Wing taping method

Start at 1 through 8 with fibre tape on the top side and then bottom side. check that you don't put a twist in the wing. When completed tape the wing in a 45 deg wrap from one end to the other don't cut the tape at the LE or TE edges.



	Drawn by: Dave Pope	Date: 30 Feb 2007
	Etrad 1 Meter Slope Soarer	NTS
Plan view cutting details		Sheet 1 of 4